

Bridge Assessment and Ranking

Town of Lunenburg, MA

May 2024

PREPARED FOR

Town of Lunenburg
520 Chase Road
Lunenburg, MA, 01462

PREPARED BY

BSC GROUP 
803 Summer Street
Boston, MA, 02127

1. Table of Contents

2. LIST OF TABLES	1-3
3. LIST OF FIGURES	1-4
CHAPTER 1: INTRODUCTION	7
1.1 SUBCHAPTER 1.1	7
CHAPTER 2: RESULTS	2-1
2.1 LANCASTER AVENUE OVER CATACOONAMUG BROOK NO. L-17-025.....	2-3
2.1.1 DEFICIENCIES	2-3
2.1.2 RECOMMENDATIONS	2-7
2.2 NEW WEST TOWNSEND ROAD OVER PEARL HILL BROOK NO. L-17-029	2-9
2.2.1 DEFICIENCIES	2-9
2.2.2 RECOMMENDATIONS	2-14
2.3 LANCASTER AVENUE OVER EASTER BROOK NO. L-17-014	2-15
2.3.1 DEFICIENCIES	2-15
2.3.2 RECOMMENDATIONS	2-19
2.4 CHASE ROAD OVER MULPUS BROOK NO. L-17-031	2-20
2.4.1 DEFICIENCIES	2-20

2.4.2 RECOMMENDATIONS	2-25
2.5 HOWARD STREET OVER MULPUS BROOK NO. L-17-030.....	2-26
2.5.1 DEFICIENCIES	2-26
2.5.2 RECOMMENDATIONS.....	2-30
2.6 WHITE STREET OVER PEARL HILL BROOK NO. L-17-001 (6RY).....	2-31
2.6.1 DEFICIENCIES	2-31
2.6.2 RECOMMENDATIONS.....	2-35
CHAPTER 3: CONCLUSIONS	2-1
CHAPTER 4: REFERENCES.....	2-2
4. APPENDICES	3-3
APPENDIX A: INSPECTION REPORTS	3-4
APPENDIX B: MATERIAL DATA SHEETS	3-5

1. LIST OF TABLES

Table 1: Structural Assessment Priority Ranking.....	2-1
Table 2: Condition Rating Guide.....	2-2



2. LIST OF FIGURES

Figure 1-1 L-17-025 North Approach	2-4
Figure 1-2 L-17-025 West end of slab	2-4
Figure 1-3 L-17-025 East end of slab	2-5
Figure 1-4 L-17-025 West End Underside.....	2-5
Figure 1-5 L-17-025 South Abutment	2-6
Figure 1-7 L-17-025 south breastwall and southeast wingwall	2-7
Figure 1-8 L-17-025 Northwest wingwall	2-7
Figure 2-1 L-17-029 West Elevation.....	2-10
Figure 2-2 L-17-029 Northeast face of abutment.....	2-10
Figure 2-3 L-17-029 North Abutment.....	2-11
Figure 2-4 L-17-029 Northeast abutment.....	2-11
Figure 2-5 L-17-029 West elevation.....	2-12
Figure 2-6 L-17-029 South Abutment	2-12
Figure 2-7 L-17-029 Southwest Corner.....	2-13
Figure 2-8 L-17-029 North abutment.....	2-13
Figure 2-9 L-17-029 Beam Flange	2-14



Figure 3-1 L-17-014 Wearing Surface.....	2-16
Figure 3-2 L-17-014 West Guardrail.....	2-16
Figure 3-3 L-17-014 East Rail.....	2-17
Figure 3-4 L-17-014 East Elevation.....	2-17
Figure 3-5 L-17-014 Upstream	2-18
Figure 3-6 L-17-014 West Elevation.....	2-18
Figure 4-1 L-17-031 East Elevation.....	2-21
Figure 4-2 L-17-031 South Abutment	2-21
Figure 4-3 L-17-031 Grout at Culvert Transition	2-22
Figure 4-4 L-17-031 Steel Pipe.....	2-22
Figure 4-5 L-17-031 Steel pipe.....	2-23
Figure 4-6 L-17-031 West Elevation Stone Beams	2-23
Figure 4-7 L-17-031 Steel pipe.....	2-24
Figure 4-8 L-17-031 Steel pipe section gap	2-24
Figure 5-1 L-17-030 Wearing Surface.....	2-27
Figure 5-2 L-17-030 Northwest Edge of Wearing Surface	2-27
Figure 5-3 L-17-030 North Elevation.....	2-28
Figure 5-4 L-17-030 Northeast Wingwall.....	2-28
Figure 5-5 L-17-030 South Elevation	2-29
Figure 5-6 L-17-030 North Elevation drainage pipe.....	2-29
Figure 6-1 L-17-001 South Elevation	2-32



Figure 6-2 L-17-001 South Elevation Pipe 1	2-32
Figure 6-3 L-17-001 North Elevation Pipe 1.....	2-33
Figure 6-4 L-17-001 North Elevation Pipe 2.....	2-33
Figure 6-5 L-17-001 Northeast Wingwall.....	2-34
Figure 6-6 L-17-001 North Elevation.....	2-34



CHAPTER 1: INTRODUCTION

1.1 SUBCHAPTER 1.1

The purpose of this report is to provide the Town of Lunenburg with a greater understanding of the bridges and culverts owned by the community. This report also provides the town with specific information on their structures, how they became deficient, and steps to prevent further deterioration. This report and priority ranking gives Lunenburg options for preventative maintenance, repairs, and possible replacement of their municipally owned bridges and culverts. There are 30 bridges and numerous culverts within town limits, of these 28 are municipally owned structures. Included in the 28 municipally owned structures are several culverts that are not currently included in MassDOT's inspection database. BSC has ranked the six most critical bridges and culverts.

The bridges and culverts chosen for this study were evaluated by their structural deficiencies, span lengths, school bus routes, emergency services, and importance to the residents and businesses of the community. The 6 chosen structures were priority ranked 1-6, with 1 being the most critical to the town's needs and the degree of structural deficiencies.

BSC reviewed available information on all the municipally owned structures consisting of MassDOT inspection and BSC's own field evaluation. Under federal guidelines, bridges with spans greater than or equal to 20'-0" in length are required to be inspected biannually. Shorter span bridges (10'-0" to 20'-0") and culverts (under 10'-0" span) are not held to the same inspection intervals.



CHAPTER 2: RESULTS

Current and previous inspection reports were reviewed for municipally owned deficient structures. Table 1 below shows the structural assessment priority ranking from most critical to least critical. The condition rating guide in Table 2 is used for MassDOT inspected bridges.

Table 1: Structural Assessment Priority Ranking

Priority Ranking	Bridge No.	BIN	Over (Facility Carried)	Under (Facility Intersected)
1	L-17-025	6T4	Lancaster Avenue	Catacoonomug Brook
2	L-17-029	767	New West Townsend Road	Pearl Hill Brook
3	L-17-014	6T3	Lancaster Avenue	Easter Brook
4	L-17-031	6T7	Chase Road	Mulpus Brook
5	L-17-030	768	Howard Street	Mulpus Brook
6	L-17-001	6RY	White Street	Pearl Hill Brook

Table 2: Condition Rating Guide

	N	NOT APPLICABLE	
	N	NOT APPLICABLE	Excellent Condition
G	9	EXCELLENT	No problem noted.
G	8	NO PROBLEM NOTED	Some minor problems.
G	7	GOOD	Structural elements show some minor deterioration.
F	6	SATISFACTORY	All primary structural elements are sound but may have minor section loss.
F	5	FAIR	Advanced section loss, deterioration, spalling or scour.
P	4	POOR	Loss of section, deterioration, spalling or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.
P	3	SERIOUS	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.
C	2	CRITICAL	Major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic, but corrective action may put it back in light use.
C	1	“IMMINENT” FAILURE	Out of service – beyond corrective action.
	0	FAILED	Out of service – beyond corrective action.



2.1 LANCASTER AVENUE OVER CATAKOONAMUG BROOK NO. L-17-025

Description

L-17-025 is a Cast-in-Place concrete rigid frame bridge that carries Lancaster Avenue over Catakoonamug Brook. The brook flows from West to East and the roadway runs in a North-South direction. The rigid frame has a clear span of 14'- 1", the curb-to-curb width is 25'- 11" and the out-to-out width is 36'- 9". The wingwalls are oriented in line with the roadway and are 6' long. There is highway guardrail on both sides of the road that runs for the length of the bridge plus the length of the wingwalls. The Functional Class of Lancaster Avenue is Rural Minor Arterial which is used by commuters and also services nearby farms and residents.

2.1.1 DEFICIENCIES

Based on the most recent MassDOT report from 3/8/2024, bridge L-17-025 has a deck rating of 5 (fair), a superstructure rating of 5 (fair), a substructure rating of 5 (fair), an approach rating of 6, and channel protection rating of 7 (satisfactory). The wearing surface has several minor cracks on the northbound lane and both approaches have a large crack spanning the width of the wearing surface (Figure 1-1).

There are several areas of significant concrete deterioration. The west end of the deck slab has a 11'- 6" long by full height spall that is 16" deep and 13" wide on the underside, with exposed rebar that is heavily corroded and exhibits significant section loss (Figure 1-2). The east elevation has a 12'-6" long by full height by 6" deep spall with exposed corroded rebar (Figure 1-3). The deck has map cracking extending up to 7'-0" long with efflorescence throughout the underside (Figure 1-4).

There is a 30' long x 20" high x 2" deep spall on the South Abutment and Southeast Wingwall at the water line (Figure 1-5). Efflorescence and hairline cracks are present and continue for the full height of the abutment. The structure is undersized for the current volume of water that passes through. According to Streamstats, an online water resources tool maintained by the USGS, the bankfull width at the location of the crossing is 23.2-feet. Debris can be seen both in the upstream and downstream directions, with the upstream debris greatly restricting flow due to large branches and other buildup (Figure 1-6).





Figure 1-1 L-17-025 North Approach



Figure 1-2 L-17-025 West end of slab





Figure 1-3 L-17-025 East end of slab




Figure 1-4 L-17-025 West End Underside





Figure 1-5 L-17-025 South Abutment



Figure 1-6 L-17-025 Upstream





Figure 1-7 L-17-025 south breastwall and southeast wingwall



Figure 1-8 L-17-025 Northwest wingwall



2.1.2 RECOMMENDATIONS

Based on the deteriorated state of the bridge, a complete bridge replacement is the most preferred option. The bridge meets all of the qualifying criteria for a MassDOT Municipal Small Bridge grant. The MassDOT Municipal Small Bridge grant is broken into two phases, Phase 1 (Design Grant) and Phase 2 (Construction Grant). MassDOT provides Phase 1 awardees with direct MassDOT-led consultant support for all design services. The design of the new bridge will meet the requirements of Massachusetts General Law Chapter 85 Section 35.

A 3-sided rigid frame bridge or a 4-sided box bridge would be the best options for a replacement. Both rigid frame and box bridges are constructed by installing several bridge units approximately 5'-0" wide, set side-by-side. The units are precast monolithically with reinforced concrete, creating a rigid connection between the bridge deck and the vertical walls. There are economical and structural advantages of using precast bridge units. Rigid frames are built with rigid connections at the corners of the units, which reduce the maximum bending moment at the center of the bridge, allowing for a shallower superstructure. The shallower superstructure depth helps maximize the bridge's hydraulic opening, optimizing the structure for meeting design flood criteria. The system also offers an economic advantage because less material is used to construct the units compared to other systems, such as concrete deck beams on cantilever abutments. The units are precast offsite, allowing for rapid installation and minimizing traffic disruption and construction cost.

A hydraulic report will be conducted to determine the size of the hydraulic opening and depth of scour based on design storm elevations. Design considerations will be made for: duration of construction, environmental impacts, hydraulic capacity, and impacts to abutters. The foundation type will depend on the recommendations of the geotechnical report.

An alternative solution would be a thorough repair of all spalled, delaminated, and other deteriorated concrete, as well as the installation of new scour protection. Ground Penetrating Radar (GPR) may be used to scan the bridge deck and substructure elements for corrosion and delamination not visible to the eye. Existing concrete that has deteriorated would be replaced with a MassDOT approved grout/concrete. Reinforcing bars that have deteriorated should be removed and new reinforcing bars would be spliced onto the existing rebar. A MassDOT approved bridge guardrail system would be installed to replace the current highway guardrail over the bridge.



2.2 NEW WEST TOWNSEND ROAD OVER PEARL HILL BROOK NO. L-17-029

Description

New West Townsend Road runs in a north-south direction over Pearl Hill Brook, which flows from west to east. The structure consists of 9 steel beams spaced approximately 3'-0" apart encased in concrete with a clear span of 6'-4". The out-to-out width of the culvert is approximately 40' and the pavement width is approximately 20'. The beams and deck are rigidly connected to the concrete abutments which are approximately 6'-2" high and there are dry-fit stone wingwalls up to 20'-0" long that run parallel with the road. The deck is 14" deep with a 12" layer of fill on top. The culvert carrying New West Townsend Road is critical to the commuters, residents living along the road, as well as emergency vehicles and school buses.

2.2.1 DEFICIENCIES

There is no MassDOT Inspection report for L-17-029; a field investigation was conducted by BSC Group on 4/17/2024. The deck, wingwalls, abutments, and channel all have major deficiencies that impact the structural stability of the culvert.

There is heavy deterioration of the concrete throughout the structure. The cast-in-place concrete abutments are approximately 3'-0" thick and appear to be unreinforced. The outside edges of each of the abutments are severely spalled at both the East and West elevations, with spalls up to 6'-0" long by 3'-0" wide and up to 10" deep (Figure 2-1). These spalls have exposed some of the larger stones (18" \pm diameter) used as aggregate. Both abutments have undermining for the entire length, up to 24" deep in some locations, exposing boulders which are sitting below the abutment (Figure 2-2). Inside the culvert both abutment walls are deteriorated with spalling and delaminated concrete. At the North abutment there are a series of horizontal and vertical cracks, close to the east elevation, which start beneath the beam seat and extend down to the bottom of the abutment and are up to $\frac{1}{2}$ " wide. There are several full-length horizontal cracks on both the North and South abutments up to 1" wide with moderate amounts of efflorescence (Figure 2-3). In between the encased beams on the South abutment wall there are several areas of honeycombing. The concrete around some of the encased beams has spalled, exposing the bottom flange. The exposed portions of the steel beams exhibit heavy rust and possible section loss (Figure 2-4). The underside of the deck exhibits typical cracking, spalling and honeycombing similar to the abutment walls. The exterior of the deck slab shows various spalls, and multiple full length cracks up to $\frac{1}{2}$ " wide (Figure 2-5). There are presently no guardrails at the crossing, causing safety concerns due to the substantial drop.

The culvert is undersized for the volume of water present, which has led to the significant scour and undermining of the abutments. According to Streamstats, the bankfull width at this location is 12.9-feet.





Figure 2-1 L-17-029 West Elevation



Figure 2-2 L-17-029 Northeast face of abutment






Figure 2-3 L-17-029 North Abutment



Figure 2-4 L-17-029 Northeast abutment





Figure 2-5 L-17-029 West elevation




Figure 2-6 L-17-029 South Abutment





Figure 2-7 L-17-029 Southwest Corner



Figure 2-8 L-17-029 North abutment






Figure 2-9 L-17-029 Beam Flange

2.2.2 RECOMMENDATIONS

Due to the inadequate size of the current structure, it is recommended that it be replaced. Performing a hydraulic analysis would assist in determining the optimal dimensions for a replacement structure. The hydraulic opening will likely need to be increased for improved hydraulic capacity. The replacement structure would likely be a small bridge with a span greater than 10-feet, to accommodate the current bankfull width and help satisfy the requirements of the Massachusetts Stream Crossing Standards to the maximum extent practicable. If the proposed structure is 10'-0" or greater it would be required to be designed to MGL Chapter 85 Section 35 requirements.

A 3-sided rigid frame or a 4-sided box bridge would be the preliminary options for a proposed replacement. The bridge type chosen will be based on the findings of a geotechnical report. For locations with soils that have a low bearing capacity, a box bridge would be the preferred option due to the larger bearing surface. Rigid frame bridges have a higher applied bearing pressure but are preferred by environmental agencies. Considerations will also be made for duration of construction, environmental impacts, and impacts to abutters.



2.3 LANCASTER AVENUE OVER EASTER BROOK NO. L-17-014

Description

L-17-014 is a 3-barrel pipe culvert carrying Lancaster Avenue which runs in a North–South direction over Easter Brook, which flows from west to east. The pipes are numbered from South to North with pipes #1 and #2 being corrugated steel with diameters 40" and 36" and pipe #3 being reinforced concrete with a 48" diameter. The roadway width at the culvert is 38'-9". The headwall and surrounding retaining walls are constructed from dry-fit stones. Refer to the L-17-014 MassDOT culvert inspection for more information.

2.3.1 DEFICIENCIES

According to the most recent MassDOT culvert inspection from 3/8/2024, the culvert and retaining walls received a rating of 5 (fair), a channel & channel protection rating of 5 (fair), and an approach condition of 6 (satisfactory).

The wearing surface can be seen to have several cracks. There is a 10' longitudinal crack in the northbound lane and a 9' long transverse crack above pipe #3 (Figure 3-1). The west guardrail has collision damage and two bent posts (Figure 3-2). The east guardrail has moderate collision damage at the north end and is bent towards the slope (Figure 3-3). There is an area of erosion measuring the full slope height x 4' wide x 2' deep, present in the west embankment next to pipe #1 and minor erosion of the east embankment near pipe #3. Stone has been added to prevent further erosion. The headwalls on both the east and west elevations have voids up to 2' x 2' with a penetration depth of 2'. The east headwall has evidence of deformation over pipes #1 and #2 (Figure 3-4). Debris is visible in the upstream direction restricting water flow (Figure 3-5).

There is minor deformation of the steel pipes beneath the headwall at both elevations which probably occurred at the time of construction. According to the most recent MassDOT inspection report the deformation has not changed over time. The StreamStats for this location list the bankfull width as 15.5 feet, the total combined span for this crossing is 11'-4", which is inadequate for the current flow.





Figure 3-1 L-17-014 Wearing Surface



Figure 3-2 L-17-014 West Guardrail





Figure 3-3 L-17-014 East Rail




Figure 3-4 L-17-014 East Elevation





Figure 3-5 L-17-014 Upstream



Figure 3-6 L-17-014 West Elevation



2.3.2 RECOMMENDATIONS

At a minimum, the highway guardrail and dry-fit stone headwalls should be removed and replaced. The new guardrail posts shall consist of a series of steel and Control Release Terminal (CRT) wood posts with spacing specific to designs for a Long-Span Guardrail over Culvert. MassDOT approved Steel W-beam should then be installed spanning the guardrail posts on both the approaches and over the structure. To minimize maintenance concrete or masonry headwalls are recommended to be installed to retain the fill above the pipe. It is not crucial that this structure be replaced at this time but if flooding becomes a problem, or the structure is washed out, a replacement may be warranted with a precast concrete box or a larger steel pipe. The structure is currently classified in the MassDOT Database of Bridges and Culverts as a culvert, but based on the size of the pipes and the distance in between them the structure should be classified as a small bridge (10'-20'). It is recommended that a MassDOT Small Bridge Grant application be filed during the next cycle. The grant money could be used for either designing repairs to the existing structure or for the design of a replacement bridge.



2.4 CHASE ROAD OVER MULPUS BROOK NO. L-17-031

Description

Chase Road Over Mulpus Brook Bridge No. L-17-031 is a steel pipe culvert that transitions into a stone culvert. The roadway approaches from the north and south, while Mulpus Brook flows from west to east. The total length of the structure has an out-to-out distance of approximately 65' and a pavement width of 40'. There is a highway guardrail that runs along the west side of the road; there is no guardrail along the east side. The steel pipe consists of multiple bolted pipe segments extending 45' to the stone culvert. The west elevation pipe diameter is 7'-6" with a 3'-6" high stone headwall under 12" of fill. The stone wingwalls are both 10' long.

The east elevation is a stone culvert that has a square opening and is approximately 20' long before transitions into the pipe. The square culvert opening is approximately 7'-6" in width and 8'-6" in height. There are stone deck beams that are approximately 9'-6" long x 18" tall. Above the stone deck is a stone retaining wall 4' tall and 10' long. The stone wingwalls on the east elevation are both 10' long.

2.4.1 DEFICIENCIES

There are no current MassDOT inspection reports for culvert L-17-031 listed in the MassDOT Bridge Inspection Management System. BSC Group performed a field investigation of the structure on 4/17/2024.

The wearing surface over the structure has some minor cracking but otherwise appears to be in good condition. The east elevation wingwalls show several voids up to 12" wide along with loose stones (Figure 4-1). The abutment walls in the stone section of the culvert have additional voids, up to 6" in diameter, due to deteriorated grout between the stones (Figure 4-2). The stone deck beams do not have a consistent shape or width. There are large gaps and deteriorating grout at the location where the stone culvert meets the pipe culvert (Figure 4-3).

The west elevation masonry headwall and wingwalls have failing grout and show several voids up to 12" wide between the stones. There is heavy corrosion throughout the pipe and large areas of section loss at the 4 o'clock and 8 o'clock positions for most of the length of the pipe (Figure 4-4). There are several large holes throughout the pipe at other locations which measure up to 10' in length. Holes towards the bottom of the pipe show honeycombed concrete due to water intrusion (Figure 4-5). There are gaps between segments up to 3", causing sections to be misaligned. Several of the rivets have fallen out, leading to further corrosion (Figure 4-5). Streamstats list the bankfull width at this location at 18.3', with a span of 7'-6" this culvert is significantly undersized.





Figure 4-1 L-17-031 East Elevation




Figure 4-2 L-17-031 South Abutment





Figure 4-3 L-17-031 Grout at Culvert Transition



Figure 4-4 L-17-031 Steel Pipe






Figure 4-5 L-17-031 Steel pipe



Figure 4-6 L-17-031 West Elevation Stone Beams






Figure 4-7 L-17-031 Steel pipe




Figure 4-8 L-17-031 Steel pipe section gap



2.4.2 RECOMMENDATIONS

Due to the deteriorated state of the steel pipe and the stone culvert, it is recommended to completely replace the structure. Rapid construction would be essential for minimizing traffic disruptions at this busy intersection; therefore, the optimal bridge type would be either a precast 4-sided box bridge or a precast 3-sided ridged frame. The hydraulic opening for the new structure will be required to meet the Massachusetts Stream Crossing standards to the maximum extent practicable. Both types of structures utilize rigid connections to help maximize the hydraulic opening. The foundation type will depend on the recommendation of the geotechnical report. A hydraulic report should be compiled to help determine the necessary size of the hydraulic opening and the depth of scour based on design storm water volume and flow velocity. The structures would be constructed and designed in accordance with Massachusetts General Law Chapter 85 Section 35. The highway guardrail would be replaced by a MassDOT approved crash-tested guardrail system.



2.5 HOWARD STREET OVER MULPUS BROOK NO. L-17-030

Description

Howard Street runs east-west over Mulpus Brook which flows from north to south. The structure is a 4'-0" diameter corrugated steel pipe. The pavement width is 27'-0" and the out-to-out width is 38'-0". The south elevation has a stone wingwall that is 8'-0" long, and a stone wingwall that is 6'-0" long. The headwall is approximately 2'-0" tall, with another 12" of fill above. The north elevation has two 4'-0" long wingwalls and a 2'-0" tall headwall with 4" of fill above. The north elevation also has a PVC drainage pipe at the edge of the steel pipe.

2.5.1 DEFICIENCIES

There are no current MassDOT inspection reports for culvert L-17-030 listed in the MassDOT Bridge Inspection Management System, BSC Group performed a field investigation of the structure on 4/17/2024. There were deficiencies found with the steel pipes, wingwalls, headwalls, and the wearing surface.

The culvert has no guardrail present, which can be a danger to vehicular traffic due to poor visibility of the structure and close proximity of the pavement to the edge of the culvert. The wearing surface over the culvert has several transverse cracks along the east approach (Figure 5-1). Close to the north elevation there is a 12" diameter pothole approximately 12" deep which is filled with debris. The hole is located directly above the wingwall and at the edge of the pavement (Figure 5-2).

Both the south and north elevations have headwalls with missing stones and large voids up to 8" wide. The large gaps and encroaching vegetation are causing debris to accumulate between the stones (Figure 5-3 & 5-4). The pipe south elevation can be seen with full section loss towards the waterline (Figures 5-5). The wingwalls have similar issues, with several loose stones as well. The pipes have heavy rust towards the bottom, with the north and south elevations both experiencing areas of section loss up to 5' long. The pipe at the north elevation has moderate deformation and has a large amount of debris, restricting flow downstream (Figure 5-5). Streamstats list the bankfull width at this location at 12.2' making the current 4'-0" diameter pipe significantly undersized for this crossing.





Figure 5-1 L-17-030 Wearing Surface



Figure 5-2 L-17-030 Northwest Edge of Wearing Surface





Figure 5-3 L-17-030 North Elevation




Figure 5-4 L-17-030 Northeast Wingwall





Figure 5-5 L-17-030 South Elevation



Figure 5-6 L-17-030 North Elevation drainage pipe



2.5.2 RECOMMENDATIONS

Due to the inadequate size of the culvert, it is recommended that it be replaced. A hydraulic analysis would assist in determining the appropriate opening dimensions. The hydraulic opening of the existing culvert will likely need to be increased for improved hydraulic capacity. Roadway alignment would likely remain the same. A geotechnical investigation and hydraulic analysis would assist in determining the appropriate structure type. Due to the bankfull width being 12.2', the replacement would likely be a small bridge (10'-0" +). If the proposed structure is 10'-0" or greater it would be required to be designed to MGL Chapter 85 Section 35 requirements.

The preliminary bridge option for a proposed replacement would be either a precast 4-sided box bridge or precast 3-sided rigid frame bridge with precast wingwalls and a new guardrails system. The type of bridge chosen will be largely based on the existing soil properties. A box bridge has more bearing surface area resulting in reduced applied bearing pressure. This is beneficial if the existing soils have low bearing capacity. Rigid frame bridges have higher applied bearing pressures but are generally preferred by environmental agencies.



2.6 WHITE STREET OVER PEARL HILL BROOK NO. L-17-001

Description

White Street runs east to west over Pearl Brook which flows from north to south. The structure consists of two steel pipes 55" and 52" in diameter and each elevation is surrounded by masonry stone with mortar. The roadway is 27'-0" wide and the steel pipes are both 45'-0" long. The stone headwall on the north elevation is 4'-7" high with no fill above. The headwall on the south elevation is 24" high with 6" of fill above. The south elevation stone wingwalls are each 8'-0" long and there are 15" diameter concrete drainage pipes on either side of the bridge structure. The northeast wingwall measures 6' in length and the northwest wingwall measures 8' in length.

2.6.1 DEFICIENCIES

There are no current MassDOT inspection reports for culvert L-17-001 listed in the MassDOT Bridge Inspection Management System, BSC Group conducted a field investigation of the structure on 4/17/2024. There were deficiencies found with the steel pipes, wingwalls, and headwalls.

There are no guardrails on either side of the road over the structure, which can pose a major hazard to oncoming vehicles (Figure 6-1). The steel pipes both have section loss up to 2' long and 3' wide below the water line (Figure 6-2). Heavy rust is present along the full length of the pipes below the water line and smaller areas of rust appear throughout the pipes (Figure 6-3). The pipes at the north elevation have debris and vegetation severely restricting flow downstream (Figure 6-4). The current will cause further blocking of the water flow by pushing small branches and leaves downstream.

Originally the structure had been fully mortared, but weathering has deteriorated much of the mortar. The headwall on the north elevation has multiple voids up to 6" long x 2" high (Figure 6-5). Several of the longer stones on the headwall show vertical cracks up to 1" wide. The wingwalls on the north elevation also show large voids between the stones where the mortar has eroded, and many stones are loose due to the lack of bonding material (Figure 6-6). Similar deficiencies with the mortar and stones are repeated on the South elevation. Streamstats list the bankfull width at this location at 21', with the span being 10'-11", this culvert is significantly undersized.






Figure 6-1 L-17-001 South Elevation



Figure 6-2 L-17-001 South Elevation Pipe 1





Figure 6-3 L-17-001 North Elevation Pipe 1



Figure 6-4 L-17-001 North Elevation Pipe 2






Figure 6-5 L-17-001 Northeast Wingwall



Figure 6-6 L-17-001 North Elevat



2.6.2 RECOMMENDATIONS

Based on the current condition, construction methods, and materials use there is no safe suitable repair to prolong the life of this structure. A complete replacement is recommended to bring the bridge up to current design/safety standards. Because the distance between the two pipes is less than half the diameter of the smallest pipe, this crossing is defined by MassDOT as a single span, the total span length of this crossing is 10'-11" which would classify the structure as a small bridge and qualify it for a MassDOT Small Bridge Grant. Multiple bridge types should be investigated including precast 3-sided rigid frames and precast 4-sided box bridges. Considerations should be made for the duration of construction, environmental impacts, hydraulic capacity, and impacts to abutters. The foundation type will depend on the recommendation of a geotechnical report. A hydraulic report will help determine the size of the hydraulic opening and the depth of scour based on the design storm event. The proposed structure would have a MassDOT approved, crash tested, guardrail system to increase public safety.



CHAPTER 3: CONCLUSIONS

BSC has investigated the available information for 28 of the inventoried town-owned bridges and culverts, as well as several structures not listed in the MassDOT Bridge Management system. Six of the most critical structures were ranked. The ranking is to provide Lunenburg with a greater understanding of the severity of the deficiencies of their bridges. The six ranked bridges have various degrees of deterioration, span lengths, and structure types.

The report presented recommended possible repair and replacement options for specified culverts and bridges. It should be noted that the possible repair and replacement options would require analysis and design before being implemented.

BSC will work with Lunenburg to secure grant funding for bridge replacement projects. We understand the financial constraints that the town is confronted with. We are hopeful this report will assist Lunenburg in pursuing additional grants and seeking MassDOT's technical and financial assistance. BSC will gladly assist Lunenburg on future grant applications as well as discussions with MassDOT.

CHAPTER 4: REFERENCES

MADOT BMS Client [Computer software on CD-ROM]. (n.d.).

MassDOT Bridges Web Application. (n.d.). Retrieved from
<http://massdot.maps.arcgis.com/apps/webappviewer/index.html?id=d42ae2ac2cb640ac992f763570ce10ed>

Part II: Conventional Construction. (n.d.). Retrieved from
<http://www.massdot.state.ma.us/highway/DoingBusinessWithUs/ManualsPublicationsForms/LRFDBridgeManual2013Edition/PartIIandPartIIIStandardDetails/PartIIConventionalConstruction.aspx>

Standard Specifications for Highways and Bridges. (n.d.). Retrieved from
<https://www.mass.gov/files/documents/2018/01/16/88StandardSpecifications.pdf>

USGS Stream Stats. (n.d.) Retrieved from <https://streamstats.usgs.gov/ss/>





4 Appendices



APPENDIX A: INSPECTION REPORTS



2-DIST

B.I.N.

03

6T4

STRUCTURES INSPECTION FIELD REPORT

ROUTINE INSPECTION

BR. DEPT. NO.

L-17-025

CITY/TOWN LUNENBURG		8-STRUCTURE NO. L17025-6T4-MUN-BRI	11-Kilo. POINT 000.000	41-STATUS A:OPEN	90-ROUTINE INSP. DATE MAR 8, 2024
07-FACILITY CARRIED HWY LANCASTER AV		MEMORIAL NAME/LOCAL NAME	27-YR BUILT 1938	106-YR REBUILT 0000	YR REHAB'D (NON 106) 0000
06-FEATURES INTERSECTED WATER CATACOONAMUG BK		26-FUNCTIONAL CLASS Urban Minor Arterial	DIST. BRIDGE INSPECTION ENGINEER M. Azizi		
43-STRUCTURE TYPE 101 : Concrete Slab		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER D. Simkhovich	
107-DECK TYPE 1 : Concrete Cast-in-Place		WEATHER sunny	TEMP. (air) 0°C	TEAM MEMBERS M. A. LA O GONZALEZ	
ITEM 58		5	ITEM 59		5
DECK		DEF	SUPERSTRUCTURE		DEF
1. Wearing surface	7	-	1. Stringers	N	-
2. Deck Condition	5	S-P	2. Floorbeams	N	-
3. Stay in Place Forms	N	-	3. Floor System Bracing	N	-
4. Curbs	N	-	4. Girders or Beams	N	-
5. Median	N	-	5. Trusses - General	N	-
6. Sidewalks	N	-	a. Upper Chords	N	-
7. Parapets	N	-	b. Lower Chords	N	-
8. Railing	8	-	c. Web Members	N	-
9. Anti Missile Fence	N	-	d. Lateral Bracing	N	-
10. Drainage System	N	-	e. Sway Bracings	N	-
11. Lighting Standards	N	-	f. Portals	N	-
12. Utilities	N	-	g. End Posts	N	-
13. Deck Joints	N	-	6. Pin & Hangers	N	-
14.	N	-	7. Conn Plt's, Gussets & Angles	N	-
15.	N	-	8. Cover Plates	N	-
16.	N	-	9. Bearing Devices	N	-
CURB REVEAL (In millimeters)		E	W		
N N					
APPROACHES		DEF			
a. Appr. pavement condition	6	M-P			
b. Appr. Roadway Settlement	7	-			
c. Appr. Sidewalk Settlement	N	-			
d.	N	-			
OVERHEAD SIGNS (Y/N) (Attached to bridge)		N			
a. Condition of Welds	N	-			
b. Condition of Bolts	N	-			
c. Condition of Signs	N	-			
COLLISION DAMAGE: Please explain					
None (X) Minor () Moderate () Severe ()					
LOAD DEFLECTION: Please explain					
None (X) Minor () Moderate () Severe ()					
LOAD VIBRATION: Please explain					
None (X) Minor () Moderate () Severe ()					
Any Fracture Critical Member: (Y/N)					
Any Cracks: (Y/N)					
I-60 (Dive Report):		N	I-60 (This Report):		5
93B-U/W (DIVE) Insp		00/00/0000			

X=UNKNOWN

N=NOT APPLICABLE H=HIDDEN/INACCESSIBLE

R=REMOVED

CITY/TOWN LUNENBURG			B.I.N. 6T4	BR. DEPT. NO. L-17-025	8.-STRUCTURE NO. L17025-6T4-MUN-BRI	INSPECTION DATE MAR 8, 2024																																																																																				
ITEM 61 CHANNEL & CHANNEL PROTECTION			7	ITEM 36 TRAFFIC SAFETY		ACCESSIBILITY (Y/N/P)																																																																																				
				A. Bridge Railing B. Transitions C. Approach Guardrail D. Approach Guardrail Ends	36 COND DEF	Needed Used																																																																																				
				1 8 N N 1 8 0 8	- - - -	Lift Bucket N N Ladder N N Boat N N Waders Y Y Inspector 50 N N Rigging N N Staging N N Traffic Control N N RR Flagger N N Police N N Other: N N																																																																																				
				WEIGHT POSTING Not Applicable		TOTAL HOURS 8																																																																																				
				Actual Posting	H 3 3S2 Single N N N N	PLANS (Y/N): N																																																																																				
				Recommended Posting	N N N N	(V.C.R.) (Y/N): N																																																																																				
				Waived Date: 00/00/0000	EJDMT Date: 00/00/0000	TAPE#: _____																																																																																				
				At bridge Signs In Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility	Other Advance N S N S	List of field tests performed:																																																																																				
				CLEARANCE POSTING																																																																																						
				Not Actual Field Measurement Posted Clearance	E W ft in ft in meter X 0 0 0 0																																																																																					
				At bridge Signs In Place (Y=Yes, N=No, NR=Not Required) Legibility/Visibility	Advance E W E W																																																																																					
						If YES please give priority: HIGH () MEDIUM () LOW ()																																																																																				
RATING Rating Report (Y/N): N Date: 00/00/0000 Inspection data at time of existing rating I 58: - I 59: - I 60: - Date: 00/00/0000			Recommend for Rating or Rerating (Y/N): N REASON: _____		CONDITION RATING GUIDE (For Items 58, 59, 60 and 61)																																																																																					
<table border="1"> <thead> <tr> <th></th> <th>CODE</th> <th>CONDITION</th> <th colspan="4">DEFECTS</th> </tr> </thead> <tbody> <tr> <td></td> <td>N</td> <td>NOT APPLICABLE</td> <td colspan="4"></td> </tr> <tr> <td>G</td> <td>9</td> <td>EXCELLENT</td> <td colspan="4">Excellent condition.</td> </tr> <tr> <td>G</td> <td>8</td> <td>VERY GOOD</td> <td colspan="4">No problem noted.</td> </tr> <tr> <td>G</td> <td>7</td> <td>GOOD</td> <td colspan="4">Some minor problems.</td> </tr> <tr> <td>F</td> <td>6</td> <td>SATISFACTORY</td> <td colspan="4">Structural elements show some minor deterioration.</td> </tr> <tr> <td>F</td> <td>5</td> <td>FAIR</td> <td colspan="4">All primary structural elements are sound but may have minor section loss, cracking, spalling or scour.</td> </tr> <tr> <td>P</td> <td>4</td> <td>POOR</td> <td colspan="4">Advanced section loss, deterioration, spalling or scour.</td> </tr> <tr> <td>P</td> <td>3</td> <td>SERIOUS</td> <td colspan="4">Loss of section, deterioration, spalling or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.</td> </tr> <tr> <td>C</td> <td>2</td> <td>CRITICAL</td> <td colspan="4">Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.</td> </tr> <tr> <td>C</td> <td>1</td> <td>"IMMINENT" FAILURE</td> <td colspan="4">Major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put it back in light service.</td> </tr> <tr> <td></td> <td>0</td> <td>FAILED</td> <td colspan="4">Out of service - beyond corrective action.</td> </tr> </tbody> </table>								CODE	CONDITION	DEFECTS					N	NOT APPLICABLE					G	9	EXCELLENT	Excellent condition.				G	8	VERY GOOD	No problem noted.				G	7	GOOD	Some minor problems.				F	6	SATISFACTORY	Structural elements show some minor deterioration.				F	5	FAIR	All primary structural elements are sound but may have minor section loss, cracking, spalling or scour.				P	4	POOR	Advanced section loss, deterioration, spalling or scour.				P	3	SERIOUS	Loss of section, deterioration, spalling or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.				C	2	CRITICAL	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.				C	1	"IMMINENT" FAILURE	Major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put it back in light service.					0	FAILED	Out of service - beyond corrective action.			
	CODE	CONDITION	DEFECTS																																																																																							
	N	NOT APPLICABLE																																																																																								
G	9	EXCELLENT	Excellent condition.																																																																																							
G	8	VERY GOOD	No problem noted.																																																																																							
G	7	GOOD	Some minor problems.																																																																																							
F	6	SATISFACTORY	Structural elements show some minor deterioration.																																																																																							
F	5	FAIR	All primary structural elements are sound but may have minor section loss, cracking, spalling or scour.																																																																																							
P	4	POOR	Advanced section loss, deterioration, spalling or scour.																																																																																							
P	3	SERIOUS	Loss of section, deterioration, spalling or scour have seriously affected primary structural components. Local failures are possible. Fatigue cracks in steel or shear cracks in concrete may be present.																																																																																							
C	2	CRITICAL	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.																																																																																							
C	1	"IMMINENT" FAILURE	Major deterioration or section loss present in critical structural components or obvious vertical or horizontal movement affecting structure stability. Bridge is closed to traffic but corrective action may put it back in light service.																																																																																							
	0	FAILED	Out of service - beyond corrective action.																																																																																							
DEFICIENCY REPORTING GUIDE																																																																																										
DEFICIENCY: A defect in a structure that requires corrective action.																																																																																										
CATEGORIES OF DEFICIENCIES:																																																																																										
M= Minor Deficiency Deficiencies which are minor in nature, generally do not impact the structural integrity of the bridge and could easily be repaired. Examples include but are not limited to: Spalled concrete, Minor pot holes, Minor corrosion of steel, Minor scouring, Clogged drainage, etc.																																																																																										
S= Severe/Major Deficiency Deficiencies which are more extensive in nature and need more planning and effort to repair. Examples include but are not limited to: Moderate to major deterioration in concrete, Exposed and corroded rebars, Considerable settlement, Considerable scouring or undermining, Moderate to extensive corrosion to structural steel with measurable loss of section, etc.																																																																																										
C-S= Critical Structural Deficiency A deficiency in a structural element of a bridge that poses an extreme unsafe condition due to the failure or imminent failure of the element which will affect the structural integrity of the bridge.																																																																																										
C-H= Critical Hazard Deficiency A deficiency in a component or element of a bridge that poses an extreme hazard or unsafe condition to the public, but does not impair the structural integrity of the bridge. Examples include but are not limited to: Loose concrete hanging down over traffic or pedestrians, A hole in a sidewalk that may cause injuries to pedestrians, Missing section of bridge railing, etc.																																																																																										
URGENCY OF REPAIR:																																																																																										
I = Immediate- [Inspector(s) immediately contact District Bridge Inspection Engineer (DBIE) to report the Deficiency and to receive further instruction from him/her].																																																																																										
A = ASAP- [Action/Repair should be initiated by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) upon receipt of the Inspection Report].																																																																																										
P = Prioritize- [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].																																																																																										

CITY/TOWN LUNENBURG	B.I.N. 6T4	BR. DEPT. NO. L-17-025	8.-STRUCTURE NO. L17025-6T4-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS

BRIDGE ORIENTATION

According to the map the approaches are North and South and the elevations are East and West. This structure is a cast-in-place concrete slab with abutments labeled North and South. The brook flows from West to East. **See sketch 1.**

ITEM 58 - DECK

Item 58.1 - Wearing surface

There is minor wheel line cracking in the northbound lane. **See photo 1.**

Item 58.2 - Deck Condition

See Item 59.15.

Item 58.8 - Railing

Both bridge rails are doubled W-beam guardrail continuous with abbreviated approach rails and boxing glove ends. The Northeast end is not turned from traffic.

APPROACHES

Approaches a - Appr. pavement condition

Both approaches have isolated transverse cracking. There is minor wheel line cracking in the northbound lane. **See photo 2.**

ITEM 59 - SUPERSTRUCTURE

Item 59.15 - Slab

The West end has an 11.5' long x full height (21") x 16" deep spall x up to 16" wide along the bottom, exposing heavily corroded rebar with as little as 7/16" remaining section. **See photos 3 and 4.**

The East end has a 12.5' long x full height x 6" deep spall/delamination exposing corroded rebar. **See photo 5.**

Note: The ends of the slab are over 5' away from the edges of the roadway.

There are several longitudinal hairline cracks with efflorescence at both ends, extending up to 7' in at the West end and 3' in at the East end. Some of these cracks extend into the breastwalls at all four corners.

ITEM 60 - SUBSTRUCTURE

Item 60.1 - Abutments

Item 60.1.d - Breastwalls

Due to high water the spalls along the water line were spot checked, no additional deterioration was found.

Previous report comments:

The South breastwall has a 30' long x up to 20" high x 2" deep spall along the waterline that extends 2' into the Southeast wingwall.

Both breastwalls have hairline cracks with efflorescence at the interface with the slab at the East and West ends, heaviest at the North breastwall West end (area of highest flow).

CITY/TOWN LUNENBURG	B.I.N. 6T4	BR. DEPT. NO. L-17-025	8.-STRUCTURE NO. L17025-6T4-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS

Item 60.1.e - Wingwalls

All wingwalls but the Southeast have minor hairline map cracking with efflorescence.

TRAFFIC SAFETY

Item 36a - Bridge Railing

See Item 58.8.

Item 36c - Approach Guardrail

See Item 58.8.

Item 36d - Approach Guardrail Ends

See Item 58.8.

Sketch / Chart / Photo Log

- Sketch 1 : Location map.
- Chart 1 : Stream bed monitoring chart.
- Photo 1 : Cracking in the northbound lane.
- Photo 2 : Approach pavement cracking.
- Photo 3 : West end of the slab.
- Photo 4 : West end of the slab, underside.
- Photo 5 : East end of the slab.

CITY/TOWN
LUNENBURG

B.I.N.
6T4

BR. DEPT. NO.
L-17-025

8.-STRUCTURE NO.

L17025-6T4-MUN-BRI

INSPECTION DATE
MAR 8, 2024

SKETCHES



Sketch 1: Location map.


CITY/TOWN LUNENBURG	B.I.N. 6T4	BR. DEPT. NO. L-17-025	8.-STRUCTURE NO. L17025-6T4-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

CHARTS

SCOUR MONITORING CHART

@ Upstream/Downstream end of the structure

Measurement Location		Measurment date						
Downstream (East) end	3/8/24							
1 North wall	5.6'							
2 Center	5.7'							
3 South wall	5.7'							
Upstream (West) end								
1 North wall	6.2'							
2 Center	6.4'							
3 South wall	6.6'							



Measurement Location

Chart 1: Stream bed monitoring chart.

CITY/TOWN LUNENBURG	B.I.N. 6T4	BR. DEPT. NO. L-17-025	8.-STRUCTURE NO. L17025-6T4-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS

Photo 1: Cracking in the northbound lane.



Photo 2: Approach pavement cracking.

CITY/TOWN
LUNENBURGB.I.N.
6T4BR. DEPT. NO.
L-17-025

8.-STRUCTURE NO.

L17025-6T4-MUN-BRI

INSPECTION DATE
MAR 8, 2024**PHOTOS****Photo 3: West end of the slab.****Photo 4: West end of the slab, underside.**

CITY/TOWN LUNENBURG	B.I.N. 6T4	BR. DEPT. NO. L-17-025	8.-STRUCTURE NO. L17025-6T4-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS

Photo 5: East end of the slab.

Report Date: May 14, 2024

State Information

Classification		Code
BDEPT#= L17025	Agency Br.No.	(112) NBIS Bridge Length N
Town= Lunenburg	L.O.	(104) Highway System N
B.I.N= 6T4	AASHTO= 006.6	(26) Functional Class - 16
RANK= 0 H.I.= NA	Identification	FHWA Select List= N (6/21/2017) (100) Defense Highway 0
(8) Structure Number	L170256T4MUNBRI	(101) Parallel Structure N
(5) Inventory Route	151000000	(102) Direction of Traffic - 2-way traffic 2
(2) State Highway Department District	03	(103) Temporary Structure N
(3) County Code 027 (4) Place code	37420	(105) Federal Lands Highways 0
(6) Features Intersected	WATER CATACOONAMUG BK	
(7) Facility Carried	HWY LANCASTER AV	(20) Toll - On free road 3
(9) Location	2.6 MI N OF LEOM-SHIRL RD	(21) Maintain - Town Agency 03
(11) Kilometerpoint	0000.000	(22) Owner - Town Agency 03
(12) Base Highway Network	N	(37) Historical Significance undetermined
(13) LRS Inventory Route & Subroute	000000000000	Condition Code
(16) Latitude	42 DEG 34 MIN	27.14 SEC (58) Deck 5
(17) Longitude	71 DEG 42 MIN	44.42 SEC (59) Superstructure 5
(98) Border Bridge State Code	Share	% (60) Substructure 5
(99) Border Bridge Structure No. #		(61) Channel & Channel Protection 7
		(62) Culverts N
Structure Type and Material		Load Rating and Posting Code
(43) Structure Type Main: Concrete	Code	101 (31) Design Load - Unknown 0
Slab	Jointless bridge type:	Not applicable (63) Operating Rating Method - Allowable Stress (AS) 2
(44) Structure Type Appr:	Code	000 (64) Operating Rating 0.0
Other		(65) Inventory Rating Method - Allowable Stress (AS) 2
(45) Number of spans in main unit	001	(66) Inventory Rating 0.0
(46) Number of approach spans	0000	(70) Bridge Posting 0
(107) Deck Structure Type - Concrete Cast-in-Place	Code	1 (41) Structure - Open A
(108) Wearing Surface / Protective System:		Appraisal Code
A) Type of wearing surface - Bituminous	Code	6 (67) Structural Evaluation 3
B) Type of membrane - Unknown	Code	8 (68) Deck Geometry 3
C) Type of deck protection - None	Code	0 (69) Underclearances, vert. and horiz. N
		(71) Waterway adequacy 7
		(72) Approach Roadway Alignment 6
(27) Year Built	1938	(36) Traffic Safety Features 1 N 1 0
(106) Year Reconstructed	0000	(113) Scour Critical Bridges 6
(42) Type of Service: On - Highway	Code	15 Inspections
Under - Waterway		(90) Inspection Date 03/08/24 (91) Frequency 24 MO
(28) Lanes: On Structure	02	(92) Critical Feature Inspection: (93) CFI DATE
(29) Average Daily Traffic		(A) Fracture Critical Detail N 00 MO A) 00/00/00
(30) Year of ADT 2022 (109) Truck ADT	06 %	(B) Underwater Inspection N 00 MO B) 00/00/00
(19) Bypass, detour length	005 KM	(C) Other Special Inspection N 00 MO C) 00/00/00
		(*) Other Inspection () N 00 MO *) 00/00/00
		(*) Closed Bridge N 00 MO *) 00/00/00
		(*) UW Special Inspection N 00 MO *) 00/00/00
		(*) Damage Inspection MO *) 00/00/00
Geometric Data		Rating Loads
(48) Length of maximum span	0004.3 M	Report Date 00/00/00 H20 Type 3 Type 3S2 Type HS
(49) Structure Length	00004.6 M	Operating 0.0 0.0 0.0 0.0
(50) Curb or sidewalk: Left 00.0 M	Right 00.0 M	Inventory 0.0 0.0 0.0 0.0
(51) Bridge Roadway Width Curb to Curb	007.9 M	Field Posting
(52) Deck Width Out to Out	011.2 M	
(32) Approach Roadway Width (w/shoulders)	007.9 M	
(33) Bridge Median - No median	Code	0 Status
(34) Skew 00 DEG (35) Structure Flared	N	Posting Date 00/00/00
(10) Inventory Route MIN Vert Clear	99.99 M	2 Axle 3 Axle 5 Axle Single
(47) Inventory Route Total Horiz Clear	07.9 M	Actual
(53) Min Vert Clear Over Bridge Rdwy	99.99 M	Recommended
(54) Min Vert Underclear ref N	00.00 M	Missing Signs N Misc.
(55) Min Lat Underclear RT ref N	00.0 M	Bridge Name
(56) Min Lat Underclear LT	00.0 M	N Anti-missile fence N Acrow Panel N Jointless Bridge
		Freeze/Thaw N : Not Applicable
(38) Navigation Control - No navigation control on waterway	Code	0 # Stairs On/Adjacent 0 Stair Owner(s)
(111) Pier Protection	Code	Accessibility (Needed/Used)
(39) Navigation Vertical Clearance	000.0 M	N / N Liftbucket N / N Rigging N / N Other
(116) Vert-lift Bridge Nav Min Vert Clear	M	N / N Ladder N / N Staging
(40) Navigation Horizontal Clearance	0000.0 M	N / N Boat N / N Traffic Control
		Y / Y Wader N / N RR Flagperson
		N / N Inspector 50 N / N Police
		Inspection Hours: 008

MASSACHUSETTS DEPARTMENT OF TRANSPORTATION PAGE 1 OF 9
STRUCTURES INSPECTION FIELD REPORT

2-DIST
03

B.I.N.
6T3

CULVERT INSPECTION

BR. DEPT. NO.
L-17-014

CITY/TOWN LUNENBURG		8.-STRUCTURE NO. L17014-6T3-MUN-BRI		11-Kilo. POINT 000.000	41-STATUS A:OPEN	90-ROUTINE INSP. DATE MAR 8, 2024
07-FACILITY CARRIED HWY LANCASTER AV		MEMORIAL NAME/LOCAL NAME		27-YR BUILT 1960	106-YR REBUILT 1970	YR REHAB'D (NON 106) 0000
06-FEATURES INTERSECTED WATER EASTER BROOK		26-FUNCTIONAL CLASS Urban Minor Arterial		DIST. BRIDGE INSPECTION ENGINEER M. Azizi		
43-STRUCTURE TYPE 319 : Steel Culvert		22-OWNER Town Agency	21-MAINTAINER Town Agency	TEAM LEADER D. Simkhovich		
107-DECK TYPE N : Not applicable		WEATHER Sunny	TEMP. (air) 7°C	TEAM MEMBERS M. A. LA O GONZALEZ		
TYPE OF CULVERT:				BARRELS: (In Meters) SIZE: 0.90Wx0.90H NUMBER: 3		
SHAPE:	ROUND			DEPTH OF COVER (To the nearest tenth of a meter) E 1.8 W 1.8		
MATERIAL:	STEEL			CURB REVEAL (In millimeters) N N N		
COATING:	ASPHALT					

ITEM 62 CULVERT & RETAINING WALLS			5	Dive This Rpt. Rpt. DEF	Dive This Rpt. Rpt. DEF	Dive This Rpt. Rpt. DEF	I62 (Dive Report): N	I62 (This Report): 5					
1. Roof	N	N	-	7.Protective Coating	N	5	S-P	13.Member Alignment	N	6	-	UNDERMINING (Y/N) If YES please explain	N
2. Floor	N	N	-	8.Embankment	N	5	S-P	14.Deformation	N	5	-	COLLISION DAMAGE: Please explain	
3. Walls	N	N	-	9.Wearing Surface	N	6	M-P	15.Scour	N	7	-	None (X) Minor () Moderate () Severe ()	
4. Headwall	N	5	S-A	10.Railing	N	5	S-A	16.Settlement	N	7	-	LOAD VIBRATION: Please explain	
5. Wingwall	N	N	-	11.Sidewalks	N	N	-	17.	N	N	-	None (X) Minor () Moderate () Severe ()	
6. Pipe	N	5	S-P	12.Utilities	N	N	-	18.	N	N	-		

ITEM 61 CHANNEL & CHANNEL PROTECTION			5	Dive This Rpt. Rpt. DEF	Dive This Rpt. Rpt. DEF	Dive This Rpt. Rpt. DEF	STREAM FLOW VELOCITY:				
1.Channel Scour	N	7	-	5. Utilities	N	N	-	Tidal () High () Moderate () Low (X)			
2.Embankment Erosion	N	7	-	6.Rip-Rap/Slope Protection	N	N	-	ITEM 61 (Dive Report): N			
3.Debris	N	5	M-P	7. Aggradation	N	7	-	ITEM 61 (This Report): 5			
4.Vegetation	N	5	S-P				93b-U/W INSP DATE:	00/00/0000			

WEIGHT POSTING			H 3 3S2 Single			At bridge Advance				
Not Applicable <input checked="" type="checkbox"/>	Actual Posting		N	N	N	N	N	S	N	S
	Recommended Posting		N	N	N	N	N	S	N	S
	Waived Date: 00/00/0000		EJDMT Date: 00/00/0000		Signs In Place (Y=Yes,N=No, NR=NotRequired) Legibility/Visibility					

ITEM 36 TRAFFIC SAFETY			36	COND	DEF	ACCESSIBILITY (Y/N/P):			TOTAL HOURS 8
A. Bridge Railing	0	5	S-A	Needed Used			Needed Used		
B. Transitions	N	N	-	Ladder	N	N	Other:		
C. Approach Guardrail	1	6	M-P	Boat	N	N		N	N
D. Approach Guardrail Ends	0	6	M-P	Waders	Y	Y			

RATING	N	If YES please give priority: HIGH () MEDIUM () LOW ()		
Rating Report (Y/N):	N			
Date:	00/00/0000	Recommend for Rating or Rerating (Y/N): N		
REASON: _____				
Inspection data at time of existing rating I 62: - Date : 00/00/0000				

X=UNKNOWN

N=NOT APPLICABLE

H=HIDDEN/INACCESSIBLE

R=REMOVED

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	8.-STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
REMARKS, PHOTOS & SKETCHES				
<p>BRIDGE ORIENTATION</p> <p>According to the compass, the approaches are North and South and the elevations are East and West. This is a 3 barrel pipe culvert, with the barrel numbering beginning from South to North. Barrels #1 and #2 are corrugated steel and barrel #3 is reinforced concrete. The brook flows West to East.</p> <p>ITEM 62 - CULVERT</p> <p>Item 62.4 - Headwall</p> <p>Both dry laid stone masonry headwalls have several missing chinking stones creating small voids. Both headwalls have up to 2 foot x 2 foot areas of missing stones with 2 feet of penetration South of barrel #1 and between barrels #2 and #3. The East headwall over barrels #1 and #2 appears to be moving to the East. The stone over barrel #1 appears to be furthering the deformation to the end. See photos #1 and #2.</p> <p>Item 62.6 - Pipe</p> <p>There are minor deformations to barrels #1 and #2 that are assumed to have occurred during construction of the headwalls, which appears to be heavier in the East end. The East ends of barrels #1 and #2 were measured vertically and horizontally to document existing deformation. Readings have not changed. See photo #2.</p> <p>Item 62.7 - Protective Coating</p> <p>The asphalt coating is missing at the bottom of barrels #1 and #2. See photo #3.</p>				
CONDITION RATING GUIDE				
	CODE	CONDITION	DEFECTS	
N	NOT APPLICABLE	Use if structure is not a culvert.		
G	9 EXCELLENT	No deficiencies.		
G	8 VERY GOOD	No noticeable or noteworthy differences which affect the condition of the culvert. Insignificant scrape marks caused by drift.		
G	7 GOOD	Shrinkage cracks, light scaling, and insignificant spalling, which does not expose reinforcing steel. Insignificant damage caused by drift with not misalignment and not requiring corrective action. Some minor scouring has occurred near curtain walls, wingwalls, or pipes. Metal culverts have a smooth symmetrical curvature with superficial corrosion and no pitting.		
F	6 SATISFACTORY	Deterioration or initial disintegration, minor chloride contamination, cracking with some leaching, or spalls on concrete or masonry walls and slabs. Local minor scouring at curtain walls, wingwalls, or pipes. Metal culverts have a smooth curvature, non-symmetrical shape, significant corrosion or moderate pitting.		
F	5 FAIR	Moderate to major deterioration; or disintegration, extensive cracking and leaching, or spalls on concrete or masonry walls and slabs. Minor settlement or misalignment. Noticeable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection in one section, significant corrosion or deep pitting.		
P	4 POOR	Large spalls, heavy scaling, wide cracks, considerable efflorescence, or opened construction joints permitting loss of backfill. Considerable settlement or misalignment. Considerable scouring or erosion at curtain walls, wingwalls, or pipes. Metal culverts have significant distortion and deflection throughout, extensive corrosion or deep pitting.		
P	3 SERIOUS	Any condition described in Code 4 but which is excessive in scope. Severe movement or differential settlement of the segments, or loss of fill. Holes may exist in walls or slabs. Integral wingwalls, nearly severed from culvert. Severe scour or erosion at curtain walls, wingwalls, or pipes. Metal culverts have extreme distortion and deflection in one section, extensive corrosion, or deep pitting with scattered perforations.		
C	2 CRITICAL	Advanced deterioration of primary structural elements. Fatigue cracks in steel or shear cracks in concrete may be present or scour may have removed substructure support. Unless closely monitored it may be necessary to close the bridge until corrective action is taken.		
C	1 "IMMINENT" FAILURE	Bridge closed. Corrective action may put back in light service.		
0	FAILED	Bridge closed. Replacement necessary.		
DEFICIENCY REPORTING GUIDE				
<p>DEFICIENCY: A defect in a structure that requires corrective action.</p> <p>CATEGORIES OF DEFICIENCIES:</p> <p>M= Minor Deficiency (Examples include but are not limited to: Spalled concrete, minor to moderate corrosion to steel culverts, minor settlement or misalignment, minor scouring, minor damage to guardrail, etc.)</p> <p>S= Severe/Major Deficiency (Examples include but are not limited to: Large spalls, wide cracks, moderate to major deterioration in concrete, considerable settlement, considerable scouring or undermining, extensive corrosion and deflection in steel culverts, etc.)</p> <p>C-S= Critical Deficiency - A deficiency in a structural component or element of a bridge that poses an extrême hazard or unsafe condition to the public. (Follow-up Critical Deficiency Report must be submitted separately)</p> <p>URGENCY OF REPAIR:</p> <p>I = Immediate [Inspector(s) stay at the bridge until the District Maintenance crew or the responsible Agency crew(if not a State bridge) show up and corrective action is taken.]</p> <p>A = ASAP- [Action will be taken by the District Maintenance Engineer or the Responsible Agency (if not a State owned bridge) upon receipt of the Inspection Report].</p> <p>P = Prioritize- [Shall be prioritized by District Maintenance Engineer or the Responsible Party (if not a State owned bridge) and repairs made when funds and/or manpower is available].</p>				

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	8.-STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS

Item 62.8 - Embankment

There is erosion to the South of barrel #1 in the West embankment. The erosion is full slope height x up to 4 foot wide x 2 foot deep. There is also erosion to the South side of barrel #3 in the East embankment. Riprap has been added to prevent the slopes from eroding any further in both East and West elevations. **See photos #2 and #3.**

Item 62.9 - Wearing Surface

There is a 9 foot long moderate transverse crack above barrel #3. There is a 10 foot long x minor longitudinal crack in the Northbound lane. **See photo #4.**

Item 62.10 - Railing

The West railing has moderate collision damage with 2 bent posts. The East railing has moderate collision damage near the North end. **See photo #5 and #6.**

Item 62.13 - Member Alignment

Pipe #2 has minor misalignment at the midpoint coupling of pipe sections.

Item 62.14 - Deformation

See Item 62.6.

ITEM 61 - CHANNEL AND CHANNEL PROTECTION

Item 61.3 - Debris

The upstream channel has moderate tree debris. **See photo #7.**

Item 61.4 - Vegetation

There is heavy vegetation growth in the upstream and downstream channels. **See photo #7.**

Item 61.7 - Aggradation

Due to previous aggradation not being present at the time of the report, the condition has been raised to 7.

APPROACHES

Approaches a - Appr. pavement condition

The South approach has a full width moderate transverse crack and a longitudinal crack in the Southbound lane. **See photo #4.**

TRAFFIC SAFETY

Item 36a - Bridge Railing

Both bridge railings are single panel W-beam steel guardrail that are continuous with the approach guardrails. See Item 62.10.

Item 36c - Approach Guardrail

The Southeast approach guardrail has minor collision damage near the north end. The Northwest approach guardrail has minor collision damage near the south end. **See photo #5 and #6.**

Item 36d - Approach Guardrail Ends


The Northwest guardrail end has moderate collision damage, and the Southeast guardrail end has severe collision damage **See photos #5 and #6.**

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	8.-STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

REMARKS**Sketch / Photo Log**

Sketch 1 : Location map
Photo 1 : West elevation displaying masonry headwall and barrels #1 and #2.
Photo 2 : East elevation displaying deformed barrels and added embankment.
Photo 3 : West elevation, South embankment displaying added riprap and erosion.
Photo 4 : Wearing surface typical cracking.
Photo 5 : West rail collision damage.
Photo 6 : East rail collision damage.
Photo 7 : Upstream debris.

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	S. STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

SKETCHES**Sketch 1: Location map**

CITY/TOWN
LUNENBURGB.I.N.
6T3BR. DEPT. NO.
L-17-014

8.-STRUCTURE NO.

L17014-6T3-MUN-BRIINSPECTION DATE
MAR 8, 2024**PHOTOS**

Photo 1: West elevation displaying masonry headwall and barrels #1 and #2.



Photo 2: East elevation displaying deformed barrels and added embankment.

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	8.-STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS

Photo 3: West elevation, South embankment displaying added riprap and erosion.




Photo 4: Wearing surface typical cracking.

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	8.-STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS

Photo 5: West rail collision damage.



Photo 6: East rail collision damage.

CITY/TOWN LUNENBURG	B.I.N. 6T3	BR. DEPT. NO. L-17-014	8.-STRUCTURE NO. L17014-6T3-MUN-BRI	INSPECTION DATE MAR 8, 2024
-------------------------------	----------------------	----------------------------------	---	---------------------------------------

PHOTOS

Photo 7: Upstream debris.

Report Date: April 29, 2024

State Information

BDEPT# L17014		Classification		Code
Town= Lunenburg		Agency Br.No.		(112) NBIS Bridge Length N
B.I.N= 6T3		L.O.		(104) Highway System N
RANK= 0 H.I.= NA		AASHTO= 035.8		(26) Functional Class - 16
Identification		FHWA Select List= N (6/21/2017)		(100) Defense Highway 0
(8) Structure Number		L170146T3MUNBRI		(101) Parallel Structure N
(5) Inventory Route		151000000		(102) Direction of Traffic - 2-way traffic 2
(2) State Highway Department District		03		(103) Temporary Structure N
(3) County Code 027 (4) Place code		37420		(105) Federal Lands Highways 0
(6) Features Intersected		WATER EASTER BROOK		(110) Designated National Network N
(7) Facility Carried		HWY LANCASTER AV		(20) Toll - On free road 3
(9) Location		50 FT S OF GIBSON ST		(21) Maintain - Town Agency 03
(11) Kilometerpoint		0000.000		(22) Owner - Town Agency 03
(12) Base Highway Network		N		(37) Historical Significance built after 1949 presumed to be not eligit Z
(13) LRS Inventory Route & Subroute		000000000000		Condition Code
(16) Latitude		42 DEG 32 MIN	45.56 SEC	(58) Deck N
(17) Longitude		71 DEG 42 MIN	42.93 SEC	(59) Superstructure N
(98) Border Bridge State Code		Share	%	(60) Substructure N
(99) Border Bridge Structure No. #				(61) Channel & Channel Protection 5
				(62) Culverts 5
Structure Type and Material				
(43) Structure Type Main: Steel		Code	319	Load Rating and Posting Code
Culvert		Jointless bridge type: Not applicable		(31) Design Load - Unknown 0
(44) Structure Type Appr:		Code	000	(63) Operating Rating Method - Allowable Stress (AS) 2
Other				(64) Operating Rating 0.0
(45) Number of spans in main unit		Code	003	(65) Inventory Rating Method - Allowable Stress (AS) 2
(46) Number of approach spans			0000	(66) Inventory Rating 0.0
(107) Deck Structure Type - Not applicable		Code	N	(70) Bridge Posting 0
(108) Wearing Surface / Protective System:				(41) Structure - Open A
A) Type of wearing surface - Not applicable=no deck		Code	N	(67) Structural Evaluation 3
B) Type of membrane - Not applicable=no deck		Code	N	(68) Deck Geometry N
C) Type of deck protection - Not applicable=no deck		Code	N	(69) Underclearances, vert. and horiz. N
				(71) Waterway adequacy 7
Age and Service				
(27) Year Built		1960		(72) Approach Roadway Alignment 6
(106) Year Reconstructed		1970		(36) Traffic Safety Features 0 N 1 0
(42) Type of Service: On - Highway				(113) Scour Critical Bridges 6
Under - Waterway		Code	15	Inspections
(28) Lanes: On Structure		02	Under structure	(90) Inspection Date 03/08/24 (91) Frequency 24 MO
(29) Average Daily Traffic				(92) Critical Feature Inspection: (93) CFI DATE
(30) Year of ADT 2022 (109) Truck ADT		06	%	(A) Fracture Critical Detail N 00 MO A) 00/00/00
(19) Bypass, detour length			005 KM	(B) Underwater Inspection N 00 MO B) 00/00/00
				(C) Other Special Inspection N 00 MO C) 12/11/18
(48) Length of maximum span			0000.9 M	(*) Other Inspection () N 00 MO *) 00/00/00
(49) Structure Length			00003.3 M	(*) Closed Bridge N 00 MO *) 00/00/00
(50) Curb or sidewalk: Left		00.0	M	(*) UW Special Inspection N 00 MO *) 00/00/00
(51) Bridge Roadway Width Curb to Curb			000.0 M	(*) Damage Inspection MO *) 00/00/00
(52) Deck Width Out to Out			000.0 M	Rating Loads
(32) Approach Roadway Width (w/shoulders)			011.8 M	Report Date 00/00/00 H20 Type 3 Type 3S2 Type HS
(33) Bridge Median - No median		Code	0	Operating 0.0 0.0 0.0 0.0
(34) Skew 00 DEG (35) Structure Flared				Inventory 0.0 0.0 0.0 0.0
(10) Inventory Route MIN Vert Clear			99.99 M	Field Posting
(47) Inventory Route Total Horiz Clear			11.8 M	Status 2 Axle 3 Axle 5 Axle Single
(53) Min Vert Clear Over Bridge Rdwy			99.99 M	Actual
(54) Min Vert Underclear ref N			00.00 M	Recommended
(55) Min Lat Underclear RT ref N			00.0 M	Missing Signs N
(56) Min Lat Underclear LT			00.0 M	Misc.
Navigation Data				
(38) Navigation Control - No navigation control on waterway		Code	0	Bridge Name N Anti-missile fence N Acrow Panel N Jointless Bridge
(111) Pier Protection		Code		Freeze/Thaw N : Not Applicable
(39) Navigation Vertical Clearance			000.0 M	# Stairs On/Adjacent 0 Stair Owner(s) Accessibility (Needed/Used)
(116) Vert-lift Bridge Nav Min Vert Clear			M	N / N Liftbucket N / N Rigging N / N Other
(40) Navigation Horizontal Clearance			0000.0 M	N / N Ladder N / N Staging
				N / N Boat N / N Traffic Control
				Y / Y Wader N / N RR Flagperson
				N / N Inspector 50 N / N Police
				Inspection Hours: 008