

# IMPORTANT:

This grease trap/interceptor shall be inspected and thoroughly cleaned on a regular and frequent basis. Failure to do so could result in damage to the piping system, and the municipal or private drainage system(s).

Per the Massachusetts Uniform State Plumbing Code 248 CMR 10:09, all establishments are required to post Maintenance Log(s), which shall be posted at all times in a visible location near the grease trap. In addition, a laminated sign shall be stenciled on or in the immediate area of the grease trap or interceptor in letters one-inch high